
#### STEP #3 - STITCH DRAWSTRING BAG:




Stitch the fabric around the two sides of the bag. IN THIS ORDER:


- a. Set stitch length to a 5. Use a 1/4" seam allowance, stitch from the top of the bag to the casing marking.
- **b.** At the casing marking, put a little backstitch
- at the mark. c. Change the stitch length to a 2 (original setting)
- d. Stitch the side of the bag, down to the bottom.
- PIVOT THE CORNERS.
- e. Stitch across the bottom of the bag, Backstitch.

# STEP #4 - EDGE FINISHES:

PRESS open seam allowance section at 1. Put a little clip at the CASING MARK. the top of the bag, on both sides.




3. ZIG-ZAG FINISH around the TOP EDGE of the bag so it makes an open circle.



**ZIG ZAG FINISH** SETTINGS:

A. Set the Machine to Stitch #2. B. Change the settings back to the original settings for THIS

4. ZIG-ZAG FINISH the SIDES and BOTTOM of the bag.



mark, stitch the edges around the sides and bottom of the C. Make sure the stitch is

stitching over the edge of the fabric. (on and off the edge).




RICE PAK & DRAWSTRING BAG INSTRUCTION SHEET GRADING CATEGORY #3 ~ FINISH WORK ~

## CHECKPOINT **STOP - GET A SIGN-OFF**

# STEP #5 - FORM THE CASING

- 1. FOLD the top edge down so that the top edge matches up with the CASING LINE.
- 2. PRESS the the fold so that it creases.
- 3. Match the top edge of the fabric to the CENTER STITCH LINE.
- 4. ZIG-ZAG stitch over the ZIG-ZAG finish stitch that you just made on the edge.


5. TRIM the corners. DO NOT cut your stitches in the corners.



### STEP #6 - DRAWSTRING


A. Get your drawstring from the teacher.

B. Attach a pin to the end of the drawstring.



C. Insert the safety pin as shown. DIAGRAM: POINT A

D. Pull the string through the casing all the way around, so it comes out the same side as it went in. DIAGRAM: POINT B



ends. (MAKE SURE ENDS ARE

together in a knot, as shown.

EXACTLY EVEN). Tie them

**DEFINITIONS:** 

BASTE: Change your stitch length to a 5 to make a temporary stitch. ! CASING: An opening for elastic or drawstring to go through.

POINT C

CHECKPOINT - STOP - GET A SIGN-OFF